BEST AVAILABLE COPY

·	. 1 1						
Grander A pressure :							. More
Distem Hafer Cli A Ch	<u>1 D</u>	Ch F	iter LL A l	L B <u>Program</u>	MISC, A	LL B Progr	<u>cam Mis</u>
·							:
4 51		Process Recipe	HS BAKE		· ·	<u> </u>	
*• <u>•</u>	SAC ANEAL						
•	Step <u>i</u>	+-Step <u>2</u>	St	tep <u>3</u>		Step 4	
	i <u>PURGE</u>	i <u>HEAT UP</u>	i <u>B</u> i	AKE	i :	COOL DOWN	
Chamber Selection		i A1			i	All	
Siep End Control	i By Time	By Time	i i	By Time	i	By Time	
Maximum Step Time 🤺	i 10 Seco	nds i 45	Seconds i	60 Secor		30 Se	conds
Temp Hode : Target	iConst Pwr: 20.	00 kWiLower PID:	1000.0 CILO	ver PID: 1000	O CHE	onst Pwr:	2.00 k
Pamp Rate : PIDs	i None : Def	ault i None :	Default i	None : Defa	uit	None : I	
iwwi: U in A: L in y	1 50 A: 40 A:	40 %1 51 %: 44	×: 44 ×1 5	i %: 44 %:	44 % .1 3	50 x: 40 x	46
Gumer A Ramp	i Constant Pwr	メ i Constant	Pwr % (Constant Pwr	* 1	Constant F)wr x
Fressure Hidde	iServo to Press	ure iControl as	Before iCon	itrol as Befo	re is	erun ta Dri	5 6 11 12 14
Taryei . Ramp Raie	1240.00 T 20.0	0 T/5i	i			30.00 T 20	
Sas Rames and Flows		i :	i	•			. 00 17
	;	i	i —	<u> </u>	;		
	;	:	i	 ;	;	 '	
	:	;:	; 	 :	<u>'</u>	•	
			; 	 '	<u>'</u> -	 :	
Proc/Elch Das Dest.	iProc: Vent Etch	: Vent iProc: Vent	Etch:VentIDro	c.Vent Etch	Uent ID		-5 - 11 1
Hain & Slit Purges	191:30.00 5: 5.0	Am/H21M·3A AA 5•	5 00m/H21N.2	00 00 0. 4 00	WEIIC 1P1	TE GO C 10	cn:ven:
	i Charting con	trol Charting	control (banting cont	moli i	55. WW 5:10	יא /אשש.
	i Expand Sten	Expand	Stan !	Evened Cton	101	Lnarting C	ontrol
Step Status/Command	i Walid Sten /	Conv I Ualid Ste	D / Copy I Us	lid Ctop / C	- ;	Expand St	<u>.</u>
Divactory Hasder	· vario ocep /	Doloto Add Bo	town Odd C	itio areb / c	ohy I (allo St p.	/ Lopy
Directory Header		DETECE MOD DE	TUTE HOOF	HILE STEE	5 / 00	<u> Hiter</u>	

EXHIBIT B